

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EX753
ESE
> 1
1.047 mi.
5528 ft.

SPILL NUMBER 0211809
711-21 BRIGHTWATER CT
BROOKLYN, NY

NY Spills S106011824
N/A

Site 1 of 2 in cluster EX

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name:	SPILL NUMBER 0211809
Address:	711-21 BRIGHTWATER CT
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0211809 / 2003-02-28
Facility ID:	0211809
Facility Type:	ER
DER Facility ID:	219824
Site ID:	269924
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2003-02-28
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2003-02-28
CID:	396
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-28
Spill Record Last Update:	2003-02-28
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CASTLE OIL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 2/28/2003-Vought-Spoke with Florence Hanley. Spill cleanup completed as of 17:00. No sewers or drains affected. Spill on concrete. Spill came out of vent pipe due to defective gauge. Vought called super (Edgar 718-769-1060) who is satisfied with cleanup. Spill closed by Vought"
Remarks:	"DUE A A DEFECTIVE GUAGE - SPEEDY DRY HAS BEEN PUT DOWN AND CLEAN UP CREW ON THE WAY."

All Materials:

Site ID:	269924
Operable Unit ID:	865258
Operable Unit:	01
Material ID:	511595
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported